

CofC

PATENT APPLICATION

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of: Examiner: Anthony T. Perry Shuji YAMADA et al. Group Art Unit: 2879 Appln. No.: 09/847,420 U.S. Patent No.: 6,815,884 B2 Filed: May 3, 2001 Issued: November 9, 2004 For: **ELECTRON SOURCE FORMING** SUBSTRATE, AND ELECTRON July 18, 2005 Certificate SOURCE AND IMAGE DISPLAY USING THE SAME JUL 2 1 2005 of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

ATTENTION: CERTIFICATE OF CORRECTIONS BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/19/2005 SSITHIB1 00000024 6815884 01 FC:1811 100.00 OP

Required Fee

Account No. 06-1205.

Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted

Attorney for Patentees

Gary M. Jacobs

Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

GMJ:ayr

4,2

DC_MAIN 198950v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S): YAMADA, et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS IN FIGURE 11:

"AMPLE" should read -- AMPULE --.

ON THE COVER PAGE AT (57) ABSTRACT

Line 8, "makes" should read --making--.

Line 9, delete ", even". Line 10, delete "elapsing longer time".

COLUMN 1:

Line 27, "Molybdenium" should read -- Molybdenum--.

Line 31, "Recio" should read -- Radio--.

COLUMN 2:

Line 6, "reveled" should read --revealed--.

COLUMN 3:

Line 66, "an" should read --a--.

COLUMN 4:

Line 6, "an" should read --a--.

Line 37, "electro-emitting" should read --electron-emitting--.

COLUMN 5:

Line 18, "iron" should read --ion--.

Line 25, "iron" should read --ion--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO.6,815,884 B2

No. of add'l. copies

@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S): YAMADA, et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 67, "view" should read --view- --.

COLUMN 7:

Line 44, "view point" should read --viewpoint--. Line 45, "view point" should read --viewpoint--.

Line 48, "view point" should read --viewpoint--.

COLUMN 8:

Line 14, "e;ectron-emitting" should read --electron-emitting--.

Line 19, "AI," should read --Al,--.

Line 40, "view point" should read --viewpoint--.

COLUMN 10:

Line 19, "an" should read -- and an--.

COLUMN 13:

Line 23, "a ample," should read -- an ampule--.

Line 37, "an" should read --a--.

COLUMN 14:

Line 44, "Doy 1" should read -- D_{ovl}--.

Line 45, "Doyn" should read -- Doyn ---.

COLUMN 15:

Line 38, "resistor 104" should read --register 104--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO.6,815,884 B2

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S): YAMADA, et al. Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 58, "Doy 1," should read -- D_{oyl} --. Line 59, "Doy n," should read -- D_{oyn} ---.

COLUMN 17:

Line 12, " Dx_{x10} " should read -- D_{x10})--. Line 65, "tow", should read --two--, and "the image forming" should read --image forming--.

COLUMN 18:

Line 29, "iron" should read --ion--.

COLUMN 19:

Line 63, "view" should read --view ---.

MAILING ADDRESS OF SENDER: FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

PATENT NO.6,815,884 B2 No. of add'l. copies @ 30¢ per page





PATENT APPLICATION

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	
		:	Examiner: Anthony T. Perry
Shuji YAMADA et al.)	
		:	Group Art Unit: 2879
Appln. No.: 09/847,420)	
		:	U.S. Patent No.: 6,815,884 B2
Filed: May 3, 2001)	
		:	Issued: November 9, 2004
For:	ELECTRON SOURCE FORMING)	
	SUBSTRATE, AND ELECTRON	:	July 18, 2005
	SOURCE AND IMAGE DISPLAY)	
	USING THE SAME	:	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

ATTENTION: CERTIFICATE OF CORRECTIONS BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Required Fee

Account No. 06-1205.

Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted

Attorney for Patentees

Gary M. Jacobs

Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
GMJ:ayr

DC_MAIN 198950v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S): YAMADA, et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS IN FIGURE 11:

"AMPLE" should read -- AMPULE --.

ON THE COVER PAGE AT (57) ABSTRACT

Line 8, "makes" should read --making--.

Line 9, delete ", even".

Line 10, delete "elapsing longer time".

COLUMN 1:

Line 27, "Molybdenium" should read -- Molybdenum--.

Line 31, "Recio" should read -- Radio--.

COLUMN 2:

Line 6, "reveled" should read --revealed--.

COLUMN 3:

Line 66, "an" should read --a--.

COLUMN 4:

Line 6, "an" should read --a--.

Line 37, "electro-emitting" should read --electron-emitting--.

COLUMN 5:

Line 18, "iron" should read --ion--.

Line 25, "iron" should read --ion--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO.6,815,884 B2

No. of add'l. copies @ 30¢ per page

 \Box

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S): YAMADA, et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 67, "view" should read --view- --.

COLUMN 7:

Line 44, "view point" should read --viewpoint--.

Line 45, "view point" should read --viewpoint--.

Line 48, "view point" should read --viewpoint--.

COLUMN 8:

Line 14, "e; ectron-emitting" should read --electron-emitting--.

Line 19, "AI," should read --Al,--.

Line 40, "view point" should read --viewpoint--.

COLUMN 10:

Line 19, "an" should read -- and an--.

COLUMN 13:

Line 23, "a ample," should read -- an ampule--.

Line 37, "an" should read --a--.

COLUMN 14:

Line 44, "Doy 1" should read --Doyl--.

Line 45, "Doyn" should read -- Doyn ---.

COLUMN 15:

Line 38, "resistor 104" should read --register 104--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO.6,815,884 B2 No. of add'l. copies

@ 30¢ per page

 \Rightarrow

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S): YAMADA, et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 58, "Doy 1," should read -- D_{oy1}--. Line 59, "Doy n," should read --D_{ovn},--.

COLUMN 17:

Line 12, " Dx_{x10} " should read -- D_{x10})--. Line 65, "tow", should read --two--, and "the image forming" should read --image forming--.

COLUMN 18:

Line 29, "iron" should read --ion--.

COLUMN 19:

Line 63, "view" should read --view- --.

MAILING ADDRESS OF SENDER: FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

PATENT NO.6,815,884 B2 No. of add'l. copies @ 30¢ per page

